ORIGINAL

25

26

27

DOCKETED BY



BEFORE THE ARIZONA CORPORATION COMMISSION 1 RECEIVED 2 **COMMISSIONERS** 2001 JUN 12 P 4: 09 3 JEFF HATCH-MILLER, CHARMA WILLIAM A. MUNDELL AZ CORP COMMISSION 4 MIKE GLEASON DOCKET CONTROL KRISTIN K. MAYES 5 **GARY PIERCE** 6 7 IN THE MATTER OF THE APPLICATION OF Docket No. SW-03575A-06-0545 PALO VERDE UTILITIES COMPANY FOR AN 8 EXTENSION OF ITS EXISTING CERTIFICATE OF CONVENIENCE AND NECESSITY. 10 IN THE MATTER OF THE APPLICATION OF Docket No. W-03576A-06-0545 SANTA CRUZ WATER COMPANY FOR AN 11 EXTENSION OF ITS EXISTING CERTIFICATE OF CONVENIENCE AND NECESSITY. 12 13 Santa Cruz Water Company, L.L.C. ("Santa Cruz") and Palo Verde Utilities Company, 14 L.L.C. ("Palo Verde")(collectively "Global Utilities"), provides notice of filing the attached 15 Arizona Department of Environmental Quality ("ADEQ") Compliance Status Report 16 demonstrating that the water provided by Santa Cruz Water Company meets all ADEQ water 17 quality standards. 18 RESPECTFULLY SUBMITTED this 12th day of June 2007. 19 20 ROSHKA DEWULF & PATTEN, PLC 21 22 Arizona Corporation Commission 23 DOCKETED Timothy J. Sabo One Arizona Center 24 JUN 12 2007 400 East Van Buren Street, Suite 800

Phoenix, Arizona 85004

26

27

Arizona Department of Environmental Quality

Drinking Water Monitoring and Protection Unit 1110 W. Washington Street, 5415B-1 Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name:	olic Water System Name: Santa Cruz Water Co.					
Public Water System ID #:	11-131					
Public Water System Type:	[X] Community	[] Non-transic	ent Non-community	[] Transient N	lon-community	
Overall Compliance Status:	[X] No Major De	ficiencies	[] Major Deficie	ncies		
Monitoring and Reporting Status: Comments:	Reporting Status: [X] No Major Defi		encies [] Major Deficienc			
Operation and Maintenance Status: Comments:	[X] No Major De	ficiencies	[] Major Deficie	ncies		
Major unresolved/ongoing operation and maintenance defic [] unable to maintain 20psi [] cross connection/backflow problems [] treatment deficiencies [] certified operator		[] ina [] sur	dequate storage face water treatmer proval of construction			
Date of last inspection / sanitary surve	y: <u>5-13-07</u>	e.		•		
Administrative Orders: Is an ADEQ administrative order in ef Comments:	fect? [] Yes	[X] N	ło			
System information:						
Number of Entry Points to the Distribution System 1		Numl	Number of Sources 3			
Population Served 29480 Servi	ice Connections 11	000 Initia	l Monitoring Year	2003		
Evaluation completed by: Jim	Puckett					
Phone: 602-771-4649 Date	: 6-11-07					

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.